Industrial Engineer

Devoted to the Maintenance and Operation of
Electrical and Associated Mechanical
Systems in Mills and Factories

Volume 84

January to December, 1926

McGRAW-HILL PUBLISHING COMPANY, INC.
10th Avenue and 36th Street
NEW YORK

UNIV. OF MINN. LIBRARY

INDUSTRIAL ENGINEER

INDEX TO VOLUME 84

January to December, 1926

GENERAL INDEX

Pages by Months

January	1 to 48
February	49 to 104
March	105 to 152
April	153 to 200
May	201 to 248
June	249 to 296
July	297 to 344
August	345 to 392
September	393 to 440
October	441 to 500
November	501 to 548
December	549 to 596

A

Accidents prevention (see Safety).
Air compressors (see Compressors).
Alarms (see Signals).
Alternator, proper foundation for (H. D. Fisher), 492.
Ammeters (see under Meters).
Ammonia compressors, power drive equipment for (Gordon Fox), *106.
Arc welding (see Welding).
Armatures (see under Motor reconnection and repair).
Association of Iron and Steel Electrical Engineers:
——Convention program, 282.
——Convention, report of, *297.

B

Babbitt (see under Bearings).
Batteries, storage:
——Boxes, cleaning dirty, 148.
——Charging:
(H. J. Achee), (Carl G. Howard), (H. H. Metzenheim), (Grady H. Emerson), (C. L. Umberger), (E. J. Evish), 583.
Generator, trouble with (E. J. Morrissey), 584.
Selecting, equipment (John H. Hertner), *171.
Bearings:
——Alignment, checking (H. E. Stafford), 330, (Donald A. Hampson), *374.
——Anti-friction, on steel mill motors (A. G. Place), *260.
——Ball:
Improper use of thrust, bearings on worm causes trouble (G. A. Luers), *146.
Installing, in lineshaft hangers (Donald A. Hampson), *424.
Lubrication of, recommendations for (H. R. Reynolds), 541.
——Babbitt:
Armature, proper, for (L. T. Miller), (Svend E. Salmonson), (J. M. Walsh), (Chester A. Williams), 32, (R. Pruger), 194.
Wire used as gage when boring (Donald A. Hampson), 44.
——Friction in, chart to determine horsepower loss from (W. F. Schaphorst), *242.
——High-pressure, selecting (E. H. Laabs), 232.
——Lubricants, equipment used for applying (Frank E. Gooding), *213.
——Lubricating motor (Frank E. Gooding), *311.
——Rebabbitting, precautions to take when, 540.
——Roller, using grooved caps to prevent oil seepage from, *95.
——Wet locations, in (Claude D. Martin), (H. D. Fisher), (E. J. Morrissey), (Donald A. Hampson), 528.
Belts (see also Motor drive).
——Age limit for a, what is the (Practical Pete), *153.
——Application and care of leather (J. R. Hopkins), *464.
——Arc of contact on drives, chart for determining, *434.
——Capacity of, under operating conditions (R. F. Jones), *165.
——Crossed-, drives, operating characteristics of (R. F. Jones), *267.
——Dressing, adjustable holder for applying stuk, *43.
——Elevator operator services, in small plant, 539.
——Maintenance kinks (W. L. Johnson), 42.
——Oily work, selecting, for (E. L. Way), (William D. Young), 286.
——Pulley for fabric-base, determining size of (W. F. Schaphorst), *339.
——Size, for this drive (E. E. Sigel), (W. F. Schaphorst), (Claude O. Streeter), (Donald A. Hampson), (J. R. Hopkins), (E. H. Laabs), (W. P. Iwen), (John B. Rafoske), *578.
Belts (Continued):
——Static on belt-driven machine, trouble with (A. C. Barker), (Donald A. Hampson), 493, (W. F. Schaphorst), 588.
——Uneven, made to run true, 338.
——Whims be your guide in laying out power drives, do not let (editorial comment), 231.
——Woodworking machines, for (Donald A. Hampson), *147.
Bonus plan to maintenance work, applying a (R. M. Hidey and Henry Hylkema), *345.
Books, practical:
——Alternating currents (Carl Edward Magnusson), 544.
——Alternating current and alternating-current apparatus, elements of (J. L. Beaver), 245.
——Belt conveyors and belt elevators (Frederick V. Hetzel, M. E.), 592.
——Coils and magnet wire (Charles R. Underhill), 103.
——Controllers for electric motors (Henry Duvall James), 544.
——Electricity and the structure of matter (L. Southerns), 103.
——Engineering, electrical (Clarence V. Christie), 245.
——Flour manufacture, process of (P. A. Amos), 245.
——Health maintenance in industries (J. D. Hackett), 103.
——Industrial electricity, part II (Chester L. Dawes), 245.
——Light, photometry and illumination engineering (Wiliam E. Barrowsl), 103.
——Lubrication, power plant (William Farrand Osborne), 103.
——Machinery erection, electrical (Terrell Croft), 103.
——Machinists' handbook, American (Fred H. Colvin and Frank A. Stanley), 544.
——Mathematics for engineers (Raymond W. Dull), 544.
——Metallurgy, engineering (Bradley Stoughton), 592.
——Motor, the induction (Herbert Vickers), 245.
——Power-factor wastes (Charles R. Underhill), 245.
——Radio, practical (James A. Moyer and John F. Wostrel), 245.
——Rewinding small motors (Daniel H. Braymer and A. C. Roe), 103.
——Safety organization, industrial (Lewis A. De Blois), 592.
——Standard (H. C. Cushing), 592.
——Transients, electric (Carl Edward Magnusson), 592.
——Transmission circuits, electrical characteristics of (William Nesbit), 592.
——Wiring, signal (Terrell Croft), 245.
——Wiring, standard (H. C. Cushing, Jr.), 544.
——Writing, English applied in technical (Clyde W. Park), 544.
Brake coil to 60-cycle service changing 25-cycle (E. H. Laabs), (Nicholas J. Weiss), (J. M. Walsh), 381.
Brushes; reducing amount of supplies in stock will lower operating costs (editorial comment), 422.
Buildings (see Plants).
Bus, connecting generator to (H. D. Fisher), (T. H. Arnold), 584.

C

Cables (see also Wire):
——Box, what causes heating of the (R. N. Vining), (E. D. Carter), (E. J. Morrissey), (D. W. Hamilton), (Charles H. McSpiritt), (Lee F. Dann), (H. Earl Heron), (William McGuire), (E. E. Sigel), *429, (H. E. Stafford), (Grady H. Emerson), (T. H. Arnold), 581.
——Joints in lead-sheath, wiping lead (Al. Fiers), (E. I. Pease), *533.
——Splices, how much insulation should be put on (Grady H. Emerson), (E. J. Morrissey), 377.
——Steel-armored, European practice in laying (P. Van Herk), 495.
——Tying small, a handy stitch for use when (A. C. Roe), *144.
Caldwell & Son Co., H. W., revamping distribution system of (J. S. Nellegar), *201.
Chain drive (see also Motor drive):
——Gears, stopping breakage of (A. B. Wray), (E. H. Laabs), *87, comment, (W. A. Warrick), 241.
——Pinion on, repairing worm flange on (Donald A. Hampson), *95.
——Silent, getting the most from (A. B. Wray), *456.
——Silent, on industrial equipment (Frank E. Gooding), *8.
——Textile mill production increase (Thomas A. Sizemore), 434.
——Woodworking machines for (Donald A. Hampson), *147.
Charts (see Records):
Circuit breaker, rewinding blowout coil (A. C. Roe), *148.
Clutches:
——Horsepower of, how to determine (K. W. Knorr), (Edward James), (J. L. Lemly), 33.
——Should not always be blamed for the trouble they may give (editorial comment), 526.
Coal (see Handling materials):
Coffin, Charles A., death of (editorial comment), 372.
Coils (see under Motor reconnection and repair):
Communication (see Signals):
Commutators (see under Motor reconnection and repair):
Compensators (see under Motor control):
Compressors:
——Air, power drive equipment for (Gordon Fox), *13, correction, 207.
——Ammonia, power drive equipment for (Gordon Fox), *106.
Conductors (see Cables and Wire):
Conduit (see also Wiring):
——Bending, measurements required for (Ovide C. Harris), (George W. Stirton), *140.
——Fishing through, by using conveyor wire (A. J. W.), 494.
——Grouping of wires in, for two-phase system (H. J. Achee), 532.
——Heating caused by carrying each phase of 3-phase circuit in separate (S. H. Samuels), 93, (C. Otto von Dannenberg), 336.
——Laying, for difficult underground installation (Grady H. Emerson), 144.
Connector for hard service, portable power (R. C. Vorderstrasse), *336.
Contest, record of accomplishment (Practical Pete), *575.
Control, motor (see Motor control):
Converters, meters used as reverse current relays prevent racing of rotary (R. C. Stevens), *335.
Conveyors:
——Billet, use of individually-driven rolls on (J. W. Corey), *588.
——Lubricating, problems in (Frank E. Gooding), *513.
Costs:
——Education in material, will help to prevent waste (editorial comment), 281.
——High operating, low price will not compensate for (editorial comment), 31.
——Maintenance, let the repair shop help to cut your (editorial comment), 83.
——Operating and maintenance, reducing, *66.
——Operating, reducing amount of supplies in stock will lower (editorial comment), 422.
——Production, money kept in the bank will not cut (editorial comment), 372.
——Today we think but next year we know (Practical Pete), *421.
Couplings on motor drives, using flexible (Gordon Fox), *561.
Cranes (see also Handling materials and Hoists):
——Lubrication of (Frank E. Gooding), *406.
——Overhead traveling, rules for safe operation of (editorial comment), 231.
——Safe operation of electric overhead traveling, rules for, 299.
——Traveling, checking alignment of bridge on (R. N. Vining), *192.

D

Demagnetizer on direct current, operating a.c. (C. Otto von Dannenberg), (W. L. Hartman), *89.
Demagnetizing a lathe (O. C. Umberger), (Donald A. Hampson), *493.
Desk lighted from beneath, construction of tracing (August Jeffers), *207.
Diagrams (see Records).
Distribution:
——Layout in candy factory (J. L. Merrill), *393.
——Revamping, system of 30-year old industrial plant (J. C. Nellegar), *201.
——Two-phase, four-wire system to two-phase, three-wire system, changing (Phil D. Comer), (A. Noeppel), (C. Otto von Dannenberg), (E. D. Carter), (W. Montelius Price), (P. Van Herk), (W. D. Hurlbut), 237.
Drawbridge, size of motor required to operate (R. F. Emerson), (E. I. Pease), 36, (E. H. Laabs), *532.

E

Editorial comments, 30, 82, 134, 182, 230, 280, 328, 372, 422, 488, 526, 576.
Electric Power Club's standards of design and performance (Practical Pete), *49.
Electromagnet (see Magnet).
Employee relations (see Job, the).
Equipment (see New equipment).

*Indicates illustrated articles

F

Factor, power (see Power factor).
Failures, daily record of all equipment (J. H. Gallant), *79.
Filing (see Records).
Fire (see also Safety).
——Departments, organization of industrial plant (A. A. Beckworth), *368.
——Extinguishing appliances, precautions to take against freezing of, 29.
——The best time to fight, is before it starts (editorial comment), 488.
Fixtures from wooden beam, suspending heavy (Nathan W. Blanchard), *238.
Furnace, electric:
——Annealing relay parts, for, *587.
——Bath, electrically-heated (Cranston H. Carpenter), *508.
Fuses:
——Clips before you blame the fuse, examine the (editorial comment), 31.
——Renewable, care of (F. D. Hewlett), 337.
——Studs, cause of heating of (E. J. Morrissey), (Harold H. Steele), (L. T. Johnson), 530.
——Testing block for plug and cartridge, simple (Nathaniel W. Blanchard), *288.

G

Gears:
——Bevel, driving pedestal emery grinder with (Donald A. Hampson), *42.
——Breakage of, stopping (A. B. Wray), (E. H. Laabs), *87, comment (W. A. Warrick), 241.
——Non-metallic, drives to prevent noise (Frank E. Gooding), *549.
——Non-metallic, use of (H. J. Achee), (Grady H. Emerson), (E. H. Laabs), (H. D. Fisher), (Donald A. Hampson), 490.
——Selection of, and pinions for steel mill service (D. W. Blakeslee), 387.
Generators:
——Battery charging, trouble with storage (E. J. Morrissey), 584.
——Bus, connection to (H. D. Fisher), (T. H. Arnold), 584.
——Concentric chain winding on a, with two-layer type, replacing (A. C. Roe), *542.
——Exciter, how single brushes caused reversal of polarity on (C. Otto von Dannenberg), 538.
——50 years ago, of (Practical Pete), *105.
——Low-voltage will not excite (Cecil W. Zimmer), (William P. Amanns), (C. Otto von Dannenberg), (Claude D. Martin), (Guy H. Wintersteen), (J. M. Zimmerman), *141, (A. C. Roe), (Donald Ferguson), (George Ringness), *235.
——Overload protection for (E. J. Morrissey), (Grady H. Emerson), 334, (C. Otto von Dannenberg), (George Cropper), *380.
——Panel to control two, layout of (J. M. Walsh), *495.
——Two-phase, winding changed to three-phase (A. C. Roe), *436.
Glass, drilling holes through plate (Robert Buckett), (Phil D. Comer), (H. D. Fisher), (Edward James), (Martin G. Lane), (J. C. Bray), 86.
Gloves, marking rubber (E. J. Morrissey), (Phil D. Comer), 376.
Grease (see Lubrication).
Grinder:
——Automobile parts, made from (J. P. Kincaid), *292.
——Pedestal emery, with bevel gears, driving (Donald A. Hampson), *42.
Grounds:
——Connections, determining resistance of (C. H. Funderberg), *535.
——Detectors for use on low-voltage systems (J. M. Zimmerman), *433.
——Testing for, method of (R. N. Vining), *40.
Growler, winding data for (Lee F. Dann), (Harry J. Achee), (Nicholas J. Weiss), *284.

H

Habits: the man who delivers the goods (Practical Pete), *1.
Handling materials (see also Conveyors, Cranes, Hoists, Trucks, etc.):
——Larry car service comparative advantages of a.c. and d.c. motors for (R. F. Emerson), *382.
——Lift and carry operations (Practical Pete), *229.
——Locomotive reduce cost of steel mill yard switching, will the oil-electric (editorial comment), 182.
——Lubrication, is your equipment getting proper (editorial comment), 422.
——Tanks, acetylene and oxygen (D. W. Blakeslee), *524.
——Tramways, interlocking control system for overhead (R. F. Emerson), *238.
——Yard switching and mill transportation (W. B. Potter and G. H. Shapter), 305.
Hangers (see Shafts).
Heating, electric (see also Furnace):
——Applying, in industrial plants (N. R. Stansel), *154.
——Association of Iron and Steel Electrical Engineers, committee report (W. P. Chandler, Jr.), 301.
——Factors that determine when, can be used to advantage (Wirt S. Scott), *272.
——Liquids and compounds, of (Lee P. Hynes), *361.
Heating system, do not include the coke-fired Salamander in your plant (editorial comment), 526.
Hoists (see also Handling materials):
——Lubrication of (Frank E. Gooding), *406.
——Motor due to mechanical cause, supposed electrical trouble with (G. H. Emerson), 337.
——Slope, motors, chart for determining horsepower of (Charles F. Cameron), *384.
Hose lines lying on floor, protecting, *143.

I

Incandescent lamps (see Lamps).
Inspection and maintenance:
——Inspection:
You can save trouble later on by overhauling equipment now (editorial comment), 329.
——Maintenance:
Are you taking advantage of the progress made in, practice? (editorial comment), 328.
Belt, kinks (W. L. Johnson), 42.
Bonus plan applied to, work (R. M. Hidey and Henry Hylkema), *345.
By-products of, do not overlook the valuable (editorial comment), 134.
Costs, let the repair shop help to cut your (editorial comment), 83.
Costs, reducing operating and, *66.
Department full credit for what it does, do you give the (editorial comment), 82.
Eighty industrial plants, practice and organization methods (G. A. Van Brunt), *57.
Mechanical, policies and practices (Hugo R. Slivinski), *61.
Studebaker Corporation, in (William Rassmussen), *50.
Welding in plant, arc (F. A. Hage-
——New equipment to chance, do not leave the care and operation of (editorial comment), 135.
Installation (see Motor installation).
Instruments (see Meters):
Insulation:
——Dirty, and high voltage are a dangerous combination (editorial comment), 30.
——Resistance and dielectric strength, comparison of (T. B. Whitson), 537.
——Resistance of electrical equipment, testing (H. E. Stafford), 585.
——Testing for faulty (R. N. Vining), *40.
——Testing, with high-frequency voltage (J. L. Rylander), *129.
——Varnishes (see Varnishes):
——Wire:
Magnet, for repair shop work, on (A. C. Roe and D. H. Braymer), *415.
Used in repair work, for (A. C. Roe and D. H. Braymer), *521.
Inventory of equipment that you need but do not have, take an (editorial comment), 31.
Iron and Steel Electrical Engineers (see Association of).

J

Job, the:
——Assistants for future plant programs, building a force of (editorial comment), 577.
——Decisions get you into trouble, do not let quick (editorial comment), 280.
——Don't forget the days when you were starting out (editorial comment), 230.
——Draw on the experience of other men in solving your problems (editorial comment), 280.
——Exchange of operating experiences, do you welcome the (editorial comment), 373.
——Have you a good job? (Practical Pete), *487.
——If you show appreciation for good work, you will get more of it (editorial comment), 135.
——Library, are you and your men taking advantage of the public? (editorial comment), 576.
——Poor work and shirked responsibility cannot be covered up forever (editorial comment), 423.
——Selecting the best method is an important part of any (editorial comment), 182.
——Thinking up good ideas is the job of everyone on the force (editorial comment), 423.
——We do not read enough or well enough (Practical Pete), *327.
Joints, simple kinks for making tight (Donald A. Hampson), 207.
Junk pile is a measure of progress, the size of the (editorial comment), 231.

L

Labor (see Job).
Lamps (see also Lighting):
——Consumption too high, is this (F. B. Williams), (D. W. Blakeslee), 185.
——Overvoltage on, may cost more than you realize (editorial comment), 135.
——Protection in atmosphere of explosive dust, 560.
Larry car service, comparative advantages of a.c. and d.c. motors for (R. F. Emerson), *382.
Lighting (see also Lamps):
——Daylight quality has many uses in industry, artificial light of (editorial comment), 422.
Lighting (Continued):
——Finish and assembly work on a moving conveyor, *335.
——Getting the most from your, system (Roy A. Palmer), *75.
——Good, costs less than nothing (editorial comment), 230.
——Paint in industrial plants, value of (M. Luckiesh and E. W. Commery), *350.
——Requirements, chart for determining (Charles F. Cameron), *93.
——Tire factory, planning a system for a (Philip Chapin Jones), *160.
——Utilization of light has lagged in the parade of progress (editorial comment), 576.
——Window, factors that influence efficiency of, 520.
——Window light, control of, 455.
——Winter preparations, don't leave the lighting system out of your (editorial comment), 489.
Lightning protection for short overhead line (H. J. Achee), (R. P. Diehl), (E. J. Morrissey), (L. T. Johnson), 531.
Lineshaft (see Shafts).
Literature (see Books and Trade literature):
Load regulating and transfer equipment, 240.
Locomotives with electric headlights, saving $740 in equipping yard (Charles A. Peterson), 494.
Lubrication:
——Applying lubricants, equipment used for (Frank E. Gooding), *213.
——Bearings, motor (Frank E. Gooding), *311.
——Bearings, of ball (H. R. Reynolds), 541.
——Conveyors, problems in (Frank E. Gooding), *513.
——Hoists and traveling cranes, of (Frank E. Gooding), *406.
——Material-handling equipment getting proper, is your (editorial comment), 422.
——Oil cups on motors, using auto tire dust caps as (J. P. Kincaid), 146.
——Power drives in industrial plants, *482.
——Specifications for oil and grease lubricants (Frank E. Gooding), *113, comment, 338.
——Wire rope, of, 349.

M

Magnet recharger, how to make a (P. Justus), (Harry J. Achee), *33.
Magnetic:
——Field, demagnitizing a watch in a d.c. (Philip N. Emigh), 292.
——Roll separates iron from Monel metal turnings, *536.
Magneto test, misleading results sometimes obtained from (George O. Powers), (Lee F. Dann), (Charles F. Cameron), (Grady H. Emerson), (T. B. Whitson), (Edward James), 139, (William H. Fredrickson), (L. L. Farrar), (C. Otto von Dannenberg), (Carl G. Howard), (L. E. Dunham), (Ovide C. Harris), 234.
Maintenance (see Inspection and——).
Materials, handling (see Handling materials).
Men (see Job).
Meters:
——Ammeter:
Motor feed gives control over quality of product, in (E. R. Feicht), 41.
Single-phase operation of motors, indicates (Lee F. Dann), 91.
——Power factor determined with watt-hour (C. Otto von Dannenberg), *431. correction, 494.
——Reactive volt-ampere indicator, what is the function of a (James B. Holston), (Frank Ammann), (L. T. Johnson), *426.
——Relays prevent racing of rotaries, used as reverse current (R. C. Stevens), *535.
——Voltmeter, checking voltages higher than capacity of (Howard Davies), *98.
——Watt-hour, determining power factor with aid of (James P. Marshall), 92.
Micrometer, measuring annular pieces with a (G. A. Luers), *542.
Mills, steel:
——Anti-friction bearings on motors for (A. G. Place), *260.
——Operation, problems of (Arthur J. Whitcomb), *249.
——Railroad electrification, economics of (O. Needham and David C. Hershberger), 306.
Motor bearings (see Bearings).
Motor control:
——Ammeter in motor feed gives control over quality of product (E. R. Feicht), 41.
——Changing control to obtain lower motor speed (E. E. Stead), *581.
——Compensators and primary resistance starters, (Arthur J. Whitcomb), *2, comments (Louis D. Moore), (H. L. Van Valkenburg), 132.
——Contactor made from a hinge, emergency (E. B. Smith), *39.
——Controller should I use for this drive, what (Arthur J. Whitcomb), *469.
——Drum controller for slip-ring motor rearranged for squirrel-cage motor (W. L. Stevens), *288.
——Induction motors, starting large (W. Montelius Price), 235.
——Interlocking of screen, prevents damage from overflow (Lee F. Dann), *432.
——Overhead tramways, interlocking control systems for (R. F. Emerson), *238.
——Overload protection, relations existing between the motor and its (C. W. Kuhn), 78.

*Indicates illustrated articles

390719

Motor control (Continued):
——Pump motors, providing sequence control for three (B. S. Havens), 536.
——Pumps for fire and service duty, automatic switching simplifies use of (L. S. Monroe), *145.
——Replace obsolete devices with modern equipment (editorial comment), 489.
——Resistance on motor controllers, changing (O. C. Callow), *276.
——Shunt motors on weak field, preventing starting (O. C. Callow), *41.
——Split-phase motors, reversing direction of rotation of, *538.
——Starters:
Primary resistance, and compensators (Arthur J. Whitcomb), *2, comments (Louis D. Moore), (H. L. Van Valkenburg), 132.
Resistance for d.c. motors, computing starting (Pierre Van Herk), *288.
——Starting:
Mounting starter without defacing building (Donald A. Hampson), *39.
Portable, device for a.c. motors (E. B. Smith), *91.
——Steam lines, panel for remote control of, *287.
——Trucks, equipment for industrial (R. B. Hunter), *219.
——Wood pulp grinders, controlling power input to (F. A. Byles), *554.
Motor drive (see also Belts, Chains, Clutches, Couplings, Gears, etc.):
——Alignment of machines with the lineshaft, checking parallel (W. W. Nichols), *387.
——Ammonia compressors, power drive equipment for (Gordon Fox), *106.
——Energy is wanted by your equipment, do you know how much (editorial comment), 488.
——Friction losses in, reducing (G. A. Van Brunt), *460, comment (H. F. Gade), 588.
——Grinder with bevel gears, driving pedestal energy (Donald A. Hampson), *42.
——Individual and small group machine drives prove economical, 291.
——Laying out, do not let whims be your guide in (editorial comment), 231.
——Layout in a candy factory (J. L. Merrill), *393.
——Lubricating power drives in industrial plants, *482.
——Machine or its drive, which is the more important, the (editorial comment), 527.
——Machine shop and pump, for (F. B. Williams), (L. B. Morrill), (Lee F. Dann), (H. D. Fisher), (E. H. Laabs), 184.
——Overloads, using breaking pins to protect against (Donald A. Hampson), *589.
——Power service layout for small (Francis A. Westbrook), *118.
Motor drive:
——Power transmission equipment manufacturers form association, 498.
——Power transmitted by friction wheels, chart for determining (W. F. Schaphorst), *290.
——Pumps, equipment for industrial (Gordon Fox), *208, *316.
——Selection of motors for industrial power drives (Philip Chapin Jones), *449.
——Speed control saves $15,000 a year, how variable (J. E. Williamson), *434.
——Transmission guards while operating, lining (Donald A. Hampson), *338.
——Trends and new practices in power drive equipment (Frank E. Gooding), *441.
Motor installation and mounting:
——Fans, reducing motor hum on large ventilating (R. F. Emerson), 334.
——Industrial-type motors (Gordon Fox), *357.
——Lineshaft coupled directly to motor, mounting (Theo. P. Barnum), *290.
——Starter without defacing building, mounting (Donald A. Hampson), *39.
Motor reconnection and repair:
——Armatures:
Banding, when power is not available (Howard Davies), *98.
Bands overheat (I. F. Wisinski), (D. W. Blakeslee), (Michael Reuter), (William Hanks), (Charles H. McSperritt), (Samuel Carbat), (Chester A. Williams), 187, (R. B. Turner), (Charles Reichenbach), (E. D. Carter), 286, (J. M. Walsh), (W. Montelius Price), (Harry J. Achee), (Lee F. Dann), *376.
Coils, mush or hit-and-miss (A. C. Roe and D. H. Braymer), *570.
Lathe for banding, inexpensive (Herbert King), *389.
Shaft when forcing commutator on, preventing bending (Samuel Carbat), 293.
Trouble caused by opening field circuit of shunt motor (Harold E. Benson), 92.
Arc on this commutator, why does this one (H. A. Nielsen), (J. M. Zimmerman), *87.
Cleaning wire-mesh carbon (Harry J. Achee), (Grady H. Emerson), 186.
Emergency demands for, in the repair shop (J. P. Collopy), 340.
Position of, and type of winding on d.c. motors, changing (A. C. Roe), *292.
Motor reconnection and repair (Continued):
——Cleaning motors, methods of (Grady H. Emerson), 436.
——Coils:
Dipping, and baking in electric oven increases motor life, 591.
Pulling and forming device, inexpensive (Arthur G. Wagoner), *543.
Rewinding job simplified by changings (A. C. Roe), 341.
——Collector rings:
Burned spots on (R. P. Diehl), (E. J. Morrissey), (H. J. Achee), (Harold H. Steele), 531.
Replacing motor, under difficulties (J. S. Murray), *191.
——Commutators:
Bars straight, trouble in keeping (C. B. Keck), (Jesse M. Zimmerman), (E. J. Morrissey), (Grady H. Emerson), (M. V. Miller), (H. E. Stafford), (George William Hanlon), *427.
Clamp for holding, together (C. B. Keck), 99.
Copper for, hard-drawn or cast (Philip M. Emigh), (William Hanks), (J. M. Walsh), (C. J. Phelps), (E. J. Morrissey), (Nicholas J. Weiss), *285.
Heating of, on rewound repulsion induction motor, (L. Konstam), 430, (Walter M. Rennick), 492.
Mica for direct current motors, selecting (Jesse M. Zimmerman), *557.
Mica segments in, care of (William L. Weber), 542.
Mica segments to save time and waste of material, cutting (C. B. Keck), *341.
Stones, development and use of (William L. Weber), *110, comments (E. H. Martindale), (H. E. Stafford), 181.
Turning (E. N. Dillard), (Nicholas J. Weiss), (Edward James), (A. C. Barker), (Harry J. Achee), (Grady H. Emerson), 88.
V-ring insulation from oil, mixture for protecting, 590.
——Compound motor to special series type, changing (A. C. Roe), *590.
——Connections cause unusual performance, improper (Dean W. Taylor), 94.
——Drying out direct-current motors (William J. Mildon), (E. J. Morrissey), 379.
——Emergency repairs and team work (Chester A. Williams), *243.
——Frequency of an induction motor, changing (A. C. Roe), 244.
——Induction, changing speed and horsepower of (H. E. Stafford), *148.
——Insulation:
Thickness of slot, increasing (P. P. Scribante), (Harry J. Achee), (C. L. Hartman), (A. C. Roe), 90.
Trimmer and wedge driver, emergency (Nicholas J. Weiss), *590.
——Nameplate data, tests on motors do not check (Frank W. Sloan), (L. T. Johnson), (James B. Halston), (Lee F. Dann), (H. E. Stafford), 429.
——Ovens for baking coils and armatures, vital factors in selection of (H. L. Grapp), 195.
——Recording rewinding data for cross connections (A. C. Roe and D. H. Braymer), *121.
——Rotors:
Reversing, motor grounded by carelessness in (Grady H. Emerson), 287.
Split-phase motors, effect of turning (C. Otto von Dannenberg), (A. C. Roe), (Edward James), (J. M. Zimmerman), 142.
——Shop:
Equipment for general (Grady H. Emerson), 137.
Steel plant, laying out electrical repair, for (Grady H. Emerson), *189.
Well-equipped electrical repair, will more than pay its way (editorial comment), 281.
——Single-phase motor for three-phase operation, changing (G. H. Emerson), (J. B. Holston), (C. L. Umberger), *530.
——Slip-ring motor to squirrel-cage type, changing (A. C. Roe), 284.
——Solder, trouble with (C. L. Phelps), (E. J. Morrissey), 284.
——Speed or number of poles in motor, chart for determining (Charles F. Cameron), *437.
——Squirrel-cage motor to wound rotor design, loss of torque in changing (R. F. Emerson), *190.
——Stall, why do these motors (C. L. Umberger), (M. E. Hall), (S. P. Cary), (G. H. Emerson), 529.
——Stators
Poles in, determined by use of compass (Michael Reuter), (Harry J. Achee), (George Cropper), (Lee F. Dann), (E. J. Morrissey), (Nicholas J. Weiss), (P. Justus), (Grady H. Emerson), 379.
Removing fan, from frames (John E. Holtman), 45.
Support for small (J. P. Kincaid), *98.
——Studebaker Corporation, in (William Rassmussen), *50.
——Synchronous, 2,200-volt, reconnected for 440-volts (W. L. Stevens), *340.
Motor reconnection and repair (Continued):
——Testing a.c. motors, simple motor-generator set for (Fred Larson), *195.
——Two-phase motors for three-phase operation, rewinding (A. C. Roe), *97.
——220 or 440 volts, connecting motor for use on (Henry Kaelin), *243.
——Washers, cutting fiber (Nicholas J. Weiss), *293.
——Winding:
Bar, from stator, removing (Michael Reuter), 543.
Calculating new, for small induction motor (Charles F. Cameron), *293.
Changing brush position and type of, on d.c. motor (A. C. Roe), *292.
Chorded split-loop, laying in a (A. C. Roe), comment (John Bantou), 44, answer (A. C. Roe), *44.
Cleaning (F. J. H. Krause), (Edward James), (J. M. Walsh), (Lee F. Dann), (H. Charlton), 38.
Cross or equalizer connections on lap (A. C. Roe and D. H. Braymer), *26.
One-coil-per-slot, to two coils per slot, changing (A. C. Roe), *196.
Pyramidal, laying out and connecting a (A. C. Roe and D. H. Braymer), *322.
Right-hand coil windings to left-hand, changing (A. C. Roe and D. H. Braymer), *177.
Rotor, for squirrel-cage motor (Edward James), 90.
Rotor, for squirrel-cage motor, calculation of (A. C. Roe), 36.
Single-phase motor, changes in (A. C. Roe and D. H. Braymer), *225.
Wire on edge, rectangular (J. M. Walsh), 425.
——Wire:
Copper, used in (A. C. Roe and D. H. Braymer), *364.
Insulation, changing (C. L. Umberger), 534.
Insulation for, used in repair work (A. C. Roe and D. H. Braymer), *521.
Magnet, insulation on (A. C. Roe and D. H. Braymer), *415.
Motor starters (see Motor control).
Motor testing (see Testing).
Motor troubles (see motor reconnection and repair).
Motors (see also motor—).
——Drawbridge, size of motor required to operate (R. F. Emerson), (E. I. Pease), 36.
——40-deg. and 50-deg. d.c., and their ratings, difference between (J. K. Witherspoon), 239.
——Induction, determining power output of (W. L. Stevens), *238.
——Mill-type:
Standardization of (A. C. Cummins), *297.
Standardize the external dimensions of (editorial comment), 135.
——Overload from, increases production, removing (Carl G. Howard), 287.
——Parallel, will two a.c. operate satisfactorily in (W. W. Lankton), (E. H. Laabs), (W. S. Pfeifer), (R. F. Emerson), (R. M. Bush), (L. J. Johnson), (R. M. Konkle), (P. P. Scribante), (Phil D. Comer), 85.
——Selection of, for industrial power drives (Philip Chapin Jones), *449.
——Series, substituted for shunt motor, specially-connected (A. J. W.), 94.
——Squirrel-cage:
Takes advantage of an easy master (editorial comment), 281.
Why not take the shackles off the (editorial comment), 30.
——Standardizing general-purpose, one more reason for (editorial comment), 488, comment (J. F. Lincoln), 536.

N

New equipment for plant operation and maintenance, *46, *100, *150, *198, *246, *294, *342, *390, *438, *496, *545, *592.
Noise, reduction of factory (editorial comment), 230.

O

Oil (see also Lubrication).
——Lubricants, specifications for grease and (Frank E. Gooding), *113, comment, 338.
——Seepage from roller bearings, using grooved caps to prevent, *95.
Ovens for tempering springs, used for, 240.

P

Paint in industrial plants, lighting value of (M. Luckiesh and E. W. Commery), *350.
Pete, Practical (see Authors' index).
Pinions or pulleys from a shaft, removing (William B. Cone), *45.
Plant, the:
——Crowded conditions, a picture study for those who work in (Practical Pete), *525.

*Indicates illustrated articles

Plant, The (Continued):
——Engineer responsible for all equipment, make a plant (editorial comment), 577.
——Heating system, do not include the coke-fired salamander in your (editorial comment), 526.
——Yard roads cost as much as good ones, poor (editorial comment), 83.
Power drives (see Motor drives).
Power factor:
——Correcting, methods of (James B. Holston), *409.
——Determining, with aid of watt-hour meter (James P. Marshall), 92, (C. Otto von Dannenberg), *431, correction, 494.
——Low, causes trouble and expense (James B. Holston), *308.
——Slide rule, determining, with (J. H. Gallant), 383.
——Revising, without the use of corrective equipment (James B. Holston), *354.
Power transmission (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.).
Power Transmission Association elects officers, 596.
Practical Pete (see Authors' index).
Protection, motor (see motor control).
Protecting devices are often worse than none at all, unsafe (editorial comment), 373.
Pulleys:
——Clutch, repairing worn shaft under loose, *541.
——Loose, trouble overcome by using steel rollers (M. C. Cockshott), *540.
——Removing pinions or, from a shaft (William B. Cone), *45.
——Removing solid, from old shafting by simple puller (M. C. Cockshott), *146.
——Size of, for fabric-base belts, determining (W. F. Schaphorst), *339.
——True improves operating conditions, keeping, 43.
Pumps, power drive equipment for industrial (Gordon Fox), *208.

Q

Qustions asked and answered by readers, *84, *136, *184, *232, *283, *330, *374, *424, *490, *528, *578.

R

"Rating" means and how it should be considered, what (editorial comment), 134.
Records:
——Belt drives, chart for determining arc of contact on, *434.
——Chart:
Horsepower loss from friction in a bearing, for determining (W. F. Schaphorst), *242.
Power transmitted by friction wheels, determining (W. F. Schaphorst), *290.
——Equipment failures, daily record of all (J. H. Gallant), *79.
——Horsepower of slope hoist motors, chart for determining (Charles F. Cameron), *384.
——Lighting requirements, handy chart for determining (Charles F. Cameron), *93.
——Motor, chart for determining speed or number of poles in (Charles F. Cameron), *437.
——Past performance, it is impossible to measure progress without (editorial comment), 372.
——Power drive data, cards for listing (J. F. Murray), *494.
——Progress of work on large installations, checking (J. B. Rakoske), 535.
——Rewinding data for cross connections, recording (A. C. Roe and D. H. Braymer), *121.
——Service, of all machines in the plant (A. J. Calhoun), *289.
Relay connection scheme correct, is this? (C. Otto von Dannenberg), (E. J. Morrissey), (Henry B. Hanstein), (Frederick Krug), (R. H. Finch), (B. J. Oparin), *331.
Repairs (see Motor reconnection and repair).
Rewinding (see Motor reconnection and repair).
Riveting steel, comparative cost of welding and (A. G. Bissell), *80.
Rope wire:
——Lubricating, 349.
——Splicing, *486.
Rotors (see Motor reconnection).

S

Safety:
——Cranes, rules for safe operating of electric overhead traveling, 299, editorial comment, 231.
——Electrical accidents cause far more than their share of losses (editorial comments), 328.
——Ground wire in conduit insures protection (S. W. Borden), *585.
——Guards while operating, during transmission (Donald A. Hampson), *338.
——Lamp protection necessary in atmosphere of explosive dust, 560.
Safety (Continued):
——Pay their way, do accident prevention and safety work (editorial comment), 526.
——Rail around machinery, rigid but demountable (G. A. Luers), *128.
——Resuscitation, can you perform the prone pressure method of (editorial comment), 83.
——Switch, lock to prevent closing of knife (C. A. Peterson), *537.
——Tools, bucket safer than handline for raising (D. W. Blakeslee), *517.
Shafts and shafting:
——Aligning parallel, easy method of (Maurice C. Cockshott), *193, comment (W. F. S.), *339.
——Ball-bearing, operating economies which resulted from installing (W. A. Atkins), 241.
——Break in service, where and why (John A. Collins, Jr.), 95.
——Greeting and aligning a lineshaft drive (George Trimm), *398, *505.
——Frozen, removed by use of oxygen lance, *539.
——Hangers:
Bearings in, installing ball (Donald A. Hampson), *424.
Two-point and four-point adjustable, comparative advantages of (E. H. Laabs), (P. L. Pryibil), 283.
——Horsepower of:
How to determine (K. W. Knorr), (Edward James), (J. L. Lemly), 33.
Transmitted by, estimating (Charles F. Cameron), *194.
——Leveling line, easily made water gage for (Donald A. Hampson), *539.
——Mule stand, how to support a (Philip N. Emigh), (J. H. Gallant), (Guy H. Wintersteen), (Svend E. Salomonsen), *136.
——Parallel, easy method of aligning (Maurice C. Cockshott), *193, comment (W. F. S.), *339.
——Pillow block, welding up steel post bracket for (M. C. Cockshott), *242.
——Pinion from, set of wedges for driving (E. E. G. Roberts), *193.
——Pinions or pulleys from, removing (William B. Cone), *45.
——Supporting, in mill type building on standard angle-iron groundwork, *241.
——Supporting, using steel forms for (P. L. Pryihil), *19.
——Worm, under loose clutch pulley repaired, *541.
Signals:
——Cement plant, types of systems used around a (T. H. Gallant), *586.
——Lamp light when telephone rings, sample relay makes (C. A. Peterson), *587.
Skylights (see Windows).
Slide rule add and subtract percentages, making the (Henry Simon), 244.
Solder and soldering:
——Cleaning stranded wire before applying (James P. Marshall), 585.
——Iron heated by a carbon arc, how to make a (D. W. Blakeslee), *388.
——Overhead work (R. C. Nason), *370.
——Trouble with, (C. L. Phelps), (E. J. Morrissey), (R. R. Schellenger), (William J. Milden), 381.
Speed reducers:
——Applications of, industrial (Frank E. Gooding), *476.
——Selection of, of proper capacity (Harry C. Peterson), *96.
——Worm gear, of proper capacity, selecting (Harry C. Peterson), *385.
Standards of design and performance (Practical Pete), *49.
Starters (see Motor control).
Static discharges, grounding machines to prevent, (E. A. Baerer), 337.
Stator (see Motor reconnection).
Steam lines, panel for remote control of, *287.
Steel Engineers (see Association of Iron and).
Steel mills (see Mills, steel).
Supervision is an expenditure that bears watching (editorial comment), 329.
Storage batteries (see Batteries).
Switches and switching).
——Automatic:
Simplifies use of pumps for fire and service duty (L. S. Monroe), *145.
Switching equipment (F. E. Jaquay), *402.
——Knife:
How often do you pull and clean your (editorial comment), 280.
Lock to prevent closing of (C. A. Peterson), *537.

T

Testing and tests:
——A. C. motors, simple motor-generator set for (Fred Larson), *195.
——Fuses:
And lamps, equipment for (William H. Frederickson), *99.
Block, simple block for (Nathaniel W. Blanchard), *288.
Flashlight for, using (William B. Cone), 143.
——Grounds, for (R. H. Vining), *40.
Testing and tests (Cintinued):
——Insulation:
Faulty, for (R. N. Vining), *40.
High frequency voltage with (J. L. Rylander), *129.
Resistance of electrical equipment, (H. E. Stafford), 585.
——Magneto, misleading results sometimes obtained from (George O. Powers), (Lee F. Dann), (Charles F. Cameron), (Grady H. Emerson), (T. B. Whitson), (Edward James), 139, (William H. Fredrickson), (L. L. Farrar), (C. Otto von Dannenberg), (Carl G. Howard), (Lie. Dunham), (Ovide C. Harris), 233.
——Transformers for various voltages, how to connect two (C. H. Founderburg), *196.
Tools:
——Clamp for straightening planks in laminated wall (W. L. Stevens), *228.
——Commutator stones, development and use of (William L. Weber), *110, comments (H. E. Martindale), (H. E. Stafford), 181.
——Hacksaw blade in close quarters, wooden stiffener permits use of (G. A. Luers), *91.
——Raising, bucket safer than handline for (D. W. Blakeslee), *517.
Tractors (see Trucks).
Trade literature you should know about, 48, 104, 152, 200, 248, 296, 344, 392, 440, 499, 548, 596.
Transformers:
——Auto—, for lighting circuits, connecting (William P. Amanns), *143.
——Capacity of, bank (I. J. Gronwold), (Frederick Krug), (Lee F. Dann), (Alexander McLennan), (Edward James), (C. Otto von Dannenberg), (Alex Bremner, Jr.), 186.
——Connecting, to three-phase circuits (L. F. Goss), *501.
——Data file, facts for your (Practical Pete), *279.
——Dirt always makes trouble (Practical Pete), *371.
——Laminations injured by burning off oil and insulating compounds, are (C. Otto von Dannenberg), 334.
——Mounting, on skid facilitates testing out new machines, 94.
——Paralleling open-delta-connected, bank with closed-delta bank (W. C. Wooley), (Frederick Nimmicke), (L. F. Goss), *333, (Philip N. Emigh), (C. Otto von Dannenberg), (A. Noeppel), 492.
——Saving made by elimination of lightly loaded, bank (E. A. Baerer), *190.
——Testing, for various voltages, how to connect two (C. H. Funderburg), *196.
——Three-phase circuits connecting, to (L. F. Goss), *565.
Transportation (see Handling materials, Trucks, etc.).
Transmission of power (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.).
Trucks, electric industrial:
——Control equipment for (R. B. Hunter), *219.
——Iron and steel industry, use of electric tractors and, in (Harold J. Payne), 303.
——Ramp for (H. D. Fisher), 84.
Turbo-generator, changing phase and voltage of (A. C. Roe), 388.

V

Varnishes, correcting usual troubles with insulating, 97.
Vehicles (see Trucks).
Ventilation: improved methods of exhausting fumes (C. D. Corwin), *518.
Voltmeter (see under Meters).

W

Washer, cutting fiber (Nicholas J. Weiss), *293.
Waste in industry, find the part you can play in furthering elimination of (editorial comment), 527.
Welding:
——Arc:
Equipment, are you getting all you should from your (editorial comment), 373.
Plant maintenance work, in (F. A. Hagedorn), *263.
Steel required in buildings, reduces, 397.
——Cans, barrels or tanks, precautions to be followed in, 481.
——Comparative cost of, and riveting steel (A. G. Bissell), *80.
——Pipe railings, fabricating all-welded, *569.
——Post bracket for pillow-block (M. C. Cockshott), *242.
——Reinforcing light metal tubing before, *341.
Winding, motor (see motor reconnection).
Windows, cleaning skylights and (J. E. Kalis), (B. C. Schlegel), 36.

*Indicates illustrated articles

Wire (see also Cable).
——Copper:
Current carrying capacity of, factors that affect safe (G. H. McKelway), 191.
Motor repair work, used in (A. C. Roe and D. H. Braymer), *364.
——Ground, placed in conduit to insure protection (S. W. Borden), *585.
Wire (Continued):
——Insulation:
Magnet, for repair shop work, on (A. C. Roe and D. H. Braymer), *415.
Repair work, for, used in (D. H. Braymer and A. C. Roe), *521.
——Kind of, where should I use this (H. E. Stafford), 493, (G. H. McKelway), 580.
——Protecting, or hose lines lying on floor, *143.
Wire (Continued):
——Pyrometer installation, on (J. S. Murray), (A. C. Barker), 89.
——Rope:
Lubricating, 349.
Splicing, *486.
——Stranded, before applying solder, cleaning (James P. Marshall), 585.
Workbench, easily-made pipe supports for (G. A. Luers), *44.

AUTHORS' INDEX

A

ACHEE, Harry J. Armature bands overheat, 376.
——Burned spots on collector rings, 531.
——Charging storage batteries, 582.
——Cleaning wire-mesh carbon brushes, 186.
——Determining number of poles in stator by use of compass, 377.
——Grouping of wires in conduit for two-phase system, 532.
——How to make a magnet recharger, *33.
——Increasing thickness of slot insulation, 90.
——Lighting protection for short overhead power line, 531.
——Turning commutators, 88.
——Use of non-metallic gears, 490.
——Winding data for growler, *284.
Adams, A. B. Reducing operating and maintenance costs, 74.
Ammann, Frank. What is the function of a reactive volt-ampere indicator?, *426.
Amanns, William P. Connecting auto-transformers for lighting circuits, *143.
——Low-voltage generator will not excite, 141.
Arnold, T. H. Connecting generator bus, 584.
——What causes heating of this cable box, 582.
Atkins, W. A. Operating economies which resulted from installing ball-bearing lineshafts, 241.

B

BAERER, E. A. Grounding machines to prevent static discharge, 337.
——Saving made by elimination of lightly loaded transformer bank, *190.
Banton, John. Comment on "Laying in a chorded split-loop winding," 44.
Barker, A. C. Trouble from static on belt-driven machine, 493.
——Turning commutators, 88.
——Wire for pyrometer installation, 89.
Barnum, Theo. P. Mounting lineshaft coupled directly to motor, *290.
Beckworth, A. A. Organization of industrial plant fire departments, *368.
Benson, Harold E. Armature trouble caused by opening field circuit of shunt motor, 92.
Bissell, A. G. Comparative cost of welding and riveting steel, *80.
Blakeslee, D. W. Armature bands overheat, 187.
——Bucket safer than handline for raising tools, *517.
——Handling acetylene and oxygen tanks, *524.
——Is this lamp consumption too high?, 185.
——Selection of gears and pinions for steel mill service, 387.
——Soldering iron heated by a carbon arc, *388.
Blanchard, Nathaniel W. Simple testing block for plug and cartridge fuses, *288.
——Suspending heavy fixtures from wooden beam, *238.
Borden, S. W. Placing ground wire in conduit insures protection, *585.
Bray, J. C. Drilling holes through plate glass, 86.
Braymer, D. H. (See A. C. Roe).
Bremner, Alex, Jr. Capacity of transformer bank, 186.
Buckett, Robert. Drilling holes through plate glass, 86.
Bush, R. M. Will two a.c. motors operate satisfactorily in parellel, 85.
Byles, F. A. Controlling power input to wood pulp grinders, *554.

C

CALHOUN, A. J. Keeping service records of all machines in the plant, *289.
Callow, O. C. Changing resistance on motor controllers, *276.
——Inexpensive way to prevent starting shunt motors on weak field, *41.
Cameron, Charles F. Calculating new winding for small induction motor, *293.
——Chart for determining horsepower of slope hoist motors, *384.
——Chart for determining lighting requirements, *93.
——Chart for determining speed or number of poles in motor, 437.
——Estimating horsepower transmitted by lineshafting, *194.
——Misleading results sometimes obtained from magneto test, 139.
Carbat, Samuel. Armature bands overheat, 187.
——Preventing bending armature shaft when forcing commutator on, 293.
Carpenter, Cranston H. Electrically-heated bath furnaces, *508.
Carter, E. D. Armature bands overheat, 286.
——Changing two-phase, four-wire system to two-phase three-wire system, 236.
——What causes heating of this cable box?, *429.
Cary, S. P. Why do these motors stall?, 529.
Case, Nathaniel E. Reducing operating and maintenance costs, 74.
Chandler, W. P., Jr. Report of electric heat committee, 301.
Charlton, H. Method of cleaning motor windings, 37.
Cockshott, Maurice C. Aligning parallel shafts, *193, comment (W.F.S.), *339.
——Simple puller for removing solid pulleys from old shafting, *146.
——Using steel rollers to overcome loose pulley trouble, *540.
——Welding up steel post bracket for pillow block, *242.
Collins, John A., Jr. Where and why lineshafts break in service, 95.
Collopy, J. P. Emergency demands for brushes in the repair shop, 340.
Comer, Phil D. Changing two-phase,, four-wire system to two-phase, three-wire system, *236.
——Drilling holes through plate glass, 86.
——Making rubber gloves, 376.
——Will two a.c. motors operate satisfactorily in parallel, 85.
Commery, E. W. (see M. Luckiesh).
Cone, William B. Flashlight for testing fuses, 143.
——Removing pinions or pulleys from a shaft, *45.
——Reducing operating and maintenance costs, 68.
Corey, J. W. Use of individually-driven rolls on billet conveyor, *588.
Corwin, C. D. Improved methods of exhausting fumes, *518.
Cropper, George. Determining number of poles in stator by use of compass, 377.
——Overload protection for generators, 380.
Cummins, A. C. Standardization of mill-type motors, *297.

D

DANN, LEE F. Ammeter indicates single-phase operation of motors, 91.
——Armature bands overheat, 376.
——Capacity of transformer bank, 186.
——Determining number of poles in stator by use of compass, 377.
——Drive for machine shop and pump, 184.
——Interlocking of screen motor control prevents damage from overflow, *432.
——Method of cleaning motor winding, 37.
——Misleading results sometimes obtained from magneto test, 138.
——Reducing operating and maintenance costs, 68.
——Tests on motors do not check nameplate data, 428.
——What causes heating of this cable box? 429.
——Winding data for growler, *284.
——Winding data for growler, *284.
Davies, Howard Banding armature when power is not available, *98.
——Checking voltages higher than capacity of voltmeter, *98.
Diehl, R. P. Burned spots on collector rings, 531.
——Lightning protection for short overhead power line, 531.
Dillard, E. N. Turning commutators, 88.
Dunham, L. E. Misleading results sometimes obtained from magneto test, 233.

E

EMERSON, G. H. Changing single-phase motor for three-phase operation, *530.
——Charging storage batteries, *583.
——Cleaning motors, 436.
——Cleaning wire-mesh carbon brushes, 186.
——Determining number of poles in stator by use of compass, *379.
——Equipment for general motor repair shop, 137.
——How much insulation should be put on cable splices, 377.
——Misleading results sometimes obtained from magneto test, 139.
——Motor grounded by carlessness in reversing motor, 287.
——Laying conduit for difficult underground installation, 144.
——Laying out electric repair shop for steel plant, *189.
——Overload protection for generators, 334.
——Supposed electrical trouble with hoist motor due to mechanical cause, 337.
——Trouble in keeping commutator bars straight, 427.
——Turning commutators, 88.
——Use of non-metallic gears, 490.
——What causes heating of this cable box? 581.
——Why do these motors stall? 529.
Emerson, R. F. Comparative advantages of ac. and d.c motors for larry car service, *382.
——Interlocking control system for overhead tramways, *238.
——Loss of torque in changing squirrel-cage motor to wound rotor design, *190.
——Reducing motor hum on large ventilating fans, 334.
——Size of motor required to operate drawbridge, 36.
——Will two a.c. motors operate satisfactorily in parallel? 85.
Emigh, Philip N. Demagnetizing a watch in a d.c. magnetic field, 292.
——Hard-drawn or cast copper for commutators, 285.
——How to support a mule stand, 136.
——Paralleling open-delta-connected transformer bank with closed-delta bank, 492.
492.
Evish, E. J. Charging storage batteries, 583.

F

FARRAR, L. L. Misleading results sometimes obtained from magneto test, 233.
Feicht, E. R. Ammeter in motor feed gives control over quality of product, 41.
Ferguson, Donald. Low-voltage generator will not excite, 235.
Fiers, Al. Wiping lead joints in lead-sheath cable, *533.
Finch, R. H. Is this relay connection scheme correct? *332.
Fisher, H. D. Bearings in wet locations, 528.
——Connecting generator to bus, 584.
——Drilling holes through plate glass, 86.
——Drive for machine shop and pump, 184.
——Proper foundation for alternator, 492.
——Ramp for industrial truck, 84.
——Reducing operating and maintenance costs, 70.
——Use of non-metallic gears, 490.
Fox, Gordon. Mounting and installing industrial-type motors, *357.
——Power drive equipment for air compressors, *13, correction, 207.
——Power drive equipment for ammonia compressors, *106.
——Power drive equipment for industrial pumps, *208, *316.
——Using flexible couplings on motor drives, *561.
Frederickson, William H. Convenient testing equipment for fuses and lamps, *99.
——Misleading results sometimes obtained from magneto test, 233.
Funderburg, C. H. Connecting two testing transformers for various voltages, *196.
——Determining resistance of ground connections, *535.

G

GADE, H. F. Comment on reducing friction losses, 588.
Gallant, J. H. How to determine power factor with slide scale, 383.
——How to support a mule stand, *137.
——Keeping a daily record of all equipment failures, *79.
——Types of signal systems used around a cement plant, *586.
Gooding, Frank E. Equipment used for applying lubricants, *213.
——Industrial applications of speed reduces, *476.
——Lubricating motor bearings, *311.
——Lubrication of hoists and traveling cranes, *406.
——Problems in lubricating conveyors, *513.
——Silent chain drives on industrial equipment, *8.
——Specifications for oil and grease lubricants, *113.
——Use of power drive equipment, *441.
——Using non-metallic gear drives to prevent noise, *549.
Goss, L. F. Connecting transformers to three-phase circuits, *501, *565.
——Paralleling open-delta-connected transformer bank with closed-delta bank, 333.
Grapp, H. L. Selection of ovens for baking coils and armatures, 195.
Gronwold, I. J. Capacity of transformer bank, 186.

H

HAGEDORN, F. A. Arc welding in plant maintenance work, *263.
Hall, M. E. Why do these motors stall? 529.
Hamilton, D. W. What causes heating of this cable box? 429.
Hampson, Donald A. Bearings in wet locations, 528.

*Indicates illustrated articles

Hampson, Donald A. (Continued):
——Best way to install ball bearings in line-shaft hangers, *424.
——Checking bearing alignment, *374.
——Demagnetizing a lathe, 493.
——Driving pedestal emery grinder with bevel gears, *42.
——Easily made water gage for leveling line shafts, *539.
——Mounting a motor starter without defacing building, *39.
——Repairing worn flange on pinion of chain drive, *95.
——Safe method of lining transmission guards while operating, *338.
——Simple kinks for making tight joints, 207.
——Size belt for drive, *579.
——Trouble with static on belt-driven machine, 493.
——Use of belt or chain drives for woodworking machines, *147.
——Use of non-metallic gears, 490.
——Using breaking pins to protect drives against overloads, *589.
——Wire used as gage when boring babbitt bearings, 44.
Hanks, William. Armature bands overheat, 187.
——Hard-drawn or cast copper for commutators, *285.
Hanlon, George William. Trouble in keeping commutator bars straight, 427.
Hanstein, Henry B. Is this relay connection scheme correct? *331.
Harris, Ovide C. Measurements required for bending conduit, *140.
——Misleading results sometimes obtained from magneto test, 233.
Hartman, C. L. Increasing thickness of slot insulation, 90.
Hartman, W. L. Operating a.c. demagnetizer on direct current, 89.
Hauswald, A. Reducing operating and maintenance costs, 73.
Havens, B. S. Providing sequence control for three pump motors, 536.
Hendricks, Lyle. Reducing operating and maintenance costs, 73.
Heron, H. Earl. What causes heating of this cable box? 429.
Hershberger, David C. (see O. Needham).
Hertner, John H. Selecting storage battery charging equipment, *171.
Hewlett, F. D. Care of renewable fuses, 337.
Hidey, R. M. and Henry Hylkema. Applying a bonus plan to maintenance work, *345.
Holston, J. B. Changing single-phase motor for three-phase operation, *530.
——Low power factor causes trouble and expense, *308.
——Methods of correcting power factor, *409.
——Raising power factor without use of corrective equipment, *354.
——Tests on motors do not check nameplate data, 428.
——What is the function of a reactive volt-ampere indicator? 426.
Holtman, John E. Removing fan stators from frames, 45.
Hopkins, J. R. Application and care of leather belt drives, *464.
——Size of belt for drive, 579.
Housley, J. Elmer. Reducing operating and maintenance costs, 69.
Howard, Carl G. Charging storage batteries, *582.
——Misleading results sometimes obtained from magneto test, 233.
——Removing overload from motors increased production, 287.
Hunter, R. B. Control equipment for industrial trucks, *219.
Hurlbut, W. O. Changing two-phase, four-wire system to two-phase, three-wire system, 236.
Hylkema, Henry (see R. M. Hidey).
Hynes, Lee P. Electric heating of liquids and compounds, *361.

I

IWEN, W. P. Size belt for drive, 579.

J

JAMES, EDWARD. Calculation of rotor winding for squirrel-cage motor, 90.
——Capacity of transformer bank, 186.
——Compensators and primary resistance starters, *7.
——Drilling holes through plate glass, 86.
——Effect of turning rotor on split-phase motors, 142.
——How to determine horsepower of a shaft or clutch, 33.
——Method of cleaning motor winding, 37.
——Misleading results sometimes obtained from magneto test, 139.
——Turning commutators, 88.
Jaquay, F. E. Using automatic switching equipment, *402.
Jeffers, August. Construction of tracing desk lighted from beneath, *207.
Johnson, L. T. Cause of heating of fuse studs, 530.
——Lightning protection for short overhead power line, 531.
——Tests on motors do not check nameplate data, 428.
——What is the function of a reactive volt-ampere indicator? 426.
——Will two a.c. motors operate satisfactorily in parallel, 85.
Jones, Philip Chapin. Planning lighting system for a tire factory, *160.
——Selection of motors for industrial power drives, *449.
Jones, R. F. Capacity of belts under operating conditions, *165.
——Operating characteristics of crossed-belt drives, *267.
Justus, P. Determining number of poles in stator by use of compass, *379.
——How to make a magnet recharger, *33.

K

KAELIN, HENRY. How to connect motor for use on 220 or 440 volts, *243.
Kalis, J. E. Cleaning skylights and windows, 36.
Keck, C. B. Cutting mica segments to save time and waste of material, *341.
——Inexpensive clamp for holding commutators together, 99.
——Trouble in keeping commutator bars straight, *427.
Kincaid, J. P. Inexpensive grinder made from automobile parts, *292.
——Support for small stators, *98.
——Using auto tire dust caps as oil cups on motors, 146.
King, Herbert. Inexpensive lathe for banding armatures, *389.
Knorr, K. W. How to determine horsepower of a shaft or clutch, 33.
Konkle, R. M. Will two a.c. motors operate satisfactorily in parallel, 85.
Konstam, L. Heating of commutator on rewound repulsion-induction motor, 430.
Krause, F. J. H. Method of cleaning motor winding, 37.
Krug, Frederick. Capacity of transformer bank, 186.
——Is this relay connection scheme correct? *331.
Kuhn, C. W. Relations existing between the motor and its overload protection, 78.

L

LAABS, E. H. Changing 25-cycle brake coil to 60-cycle service, 381.
——Comparative advantages of two-point and four-point adjustable hangers, 283.
——Drive for machine shop and pump, 184.
——Selecting high-pressure bearings, 232.
——Size belt for drive, 579.
——Size of motor required to operate drawbridge, 532.
——Stopping breakage of gears, *87.
——Use of non-metallic gears, 490.
——Will two a.c. motors operate satisfactorily in parallel? 85.
Lane, Martin G. Drilling holes through plate glass, 86.
Lankton, W. W. Reducing operating and maintenance costs, *72.
——Will two a.c. motors operate satisfactorily in parallel, 85.
Larson, Fred. Simple motor-generator set for testing a.c. motors, *195.
Lemly, J. L. How to determine horsepower of a shaft, 33.
Lincoln, J. F. Comment on standardizing general-purpose motors, 536.
Luckiesh, M. and E. W. Commery. Lighting value of paint in industrial plants, *350.
Luers, G. A. Easily-made pipe supports for workbench, *44.
——Improper use of thrust ball bearings on worm causes trouble, *146.
——Measuring annular pieces with a micrometer, *542.
——Rigid but demountable rail around machinery, *128.
——Wooden stiffener permits use of hacksaw blade in close quarters, *91.

M

MARSHALL, JAMES P. Cleaning stranded wire before applying solder, 585.
——Determining power factor with the aid of a watt-hour meter, 92.
Martin, Claude D. Bearings in wet locations, 528.
——Low-voltage generator will not excite, 141.
Martindale, E. H. Comment on development and use of commutator stones, 181.
McGuire, William. What causes heating of this cable box?, 430.
McKelway, G. H. Factors that affect safe current carrying capacity of copper wire, 191.
——Where this kind of wire should be used, 580.
McLennan, Alexander. Capacity of transformer bank, 186.
McSperritt, Charles H. Armature bands overheat, 187.
——What causes heating of this cable box?, 429.
Merrill, J. L. Layout of distribution and power drives in a small factory, *393.
Metzenheim, H. H. Charging storage batteries, 582.
Mildon, William J. Drying out direct-current motor, 379.
——Reducing operating and maintenance costs, 70.
——Trouble with solder, 381.
Miller, M. V. Trouble in keeping commutator bars straight, 427.
Miller, L. T. Proper babbitt for armature bearings, 32.
Monroe, L. S. Automatic switching simplifies use of pumps for fire and service duty, *145.
Moore, Louis D. Comments on "compensators and primary resistance starters," 132.
Morrill, L. B. Drive for machine shop and pump, 184.
Morrissey, E. J. Bearings in wet locations, 528.
——Burned spots on collector rings, 531.
——Cause of heating of fuse studs, 530.
——Determining number of poles in stator by use of compass, *378.
——Drying out direct-current motors, 379.
——Hard-drawn or cast copper for commutators, 285.
——How much insulation should be put on cable splices? 377.
——Is this relay connection scheme correct? *331.
——Lightning protection for short overhead power line, 531.
——Marking rubber gloves, 376.
——Overload protection for generators, 334.
——Trouble in keeking commutator bars straight, 427.
——Trouble with solder, 284.
——Trouble with storage battery charging generator, 584.
——What causes heating of this cable box?, 429.
Murray, J. S. Record cards for listing power drive data, *494.
——Reducing operating and maintenance costs, 67.
——Replacing motor collector ring under difficulties, *191.
——Wire for pyrometer installation, 89.

N

NASON, R. C. Soldering overhead work *370.
Needham, O. and David C. Hershberger. Economies of steel plant railroad electrification, 306.
Nellegar, J. C. Revamping distribution system, *201.
Nichols, W. W. Checking parallel alignment of machines with the lineshaft, *387.
Nielsen, H. A. Brush arcing on commutator, 87.
Nimmcke, Frederick. Paralleling open-delta-connected transformer bank with closedldeta bank, *333.
Noeppel, A. Changing two-phase, four-wire system to two-phase, three-wire system, 236.
——Paralleling open-delta-connected transformer bank with closed-delta bank, 492.

O

OPARIN, B. J. Is this relay connection scheme correct? *332.

P

PALMER, ROY A. How to get the most from your lighting system, *75.
Payne, Harold J. Use of electric industrial trucks and tractors in iron and steel industry, 303.
Pease, E. I. Size of motor required to operate drawbridge, 36.
——Wiping lead joints in lead-sheath cable, 533.
Peterson, C. A. Lock to prevent closing of knife switch, *537.
——Saving $740 in equipping yard locomotives with electric headlights, 495.
——Simple relay for lighting lamp when telephone rings, *587.
Peterson, Harry C. Factors in selection of speed reducers of proper capacity, *96.
——Selecting worm gear speed reducers of proper capacity, *385.
Pfeifer, W. S. Will two a.c. motors operate satisfactorily in parallel, 85.
Phelps, C. L. Hard-drawn or cast copper for commutators, 285.
——Trouble with solder, 284.
Place, A. G. Anti-friction bearings on steel mill motors, *260.
Potter, W. B., and G. H. Shapter. Yard switching and mill transportation, 305.
Powers, George O. Misleading results sometimes obtained from magneto test, 138.
Practical Pete. A generator of 50 years ago, *105.
——A picture study for those who work in crowded conditions, *525.
——Development and use of commutator stone, *110.
——Dirt always makes trouble, *371.
——Facts for your transformer data file, *279.
——Have you a good job? *487.
——I'm looking for information and I'm willing to pay for it, *575.
——Lift and carry operations, *229.
——Standards of design and performance, *49.
——The man who delivers the goods, *1.
——Today we think but next year we know, *421.

*Indicates illustrated articles

Practical Pete (Continued):
——We do not read enough or well enough, *327.
——What is the age limit for a leather belt, *153.
Price, W. Montelius. Armature bands overheat, 376.
——Changing two-phase, four-wire system to two-phase, three-wire system, 236.
——Starting large induction motors, 235.
Pruger, R. Selecting proper babbitt for armature bearings, 194.
Pryibil, P. L. Comparative advantages of two-point and four-point hangers, 283.
——Using steel forms for supporting lineshafting, *19.

R

RAKOSKE, J. B. Checking progress of work on large installations, 535.
——Size belt for drive, 580.
Rassmussen, William. Handling maintenance and repairs on 4,000 motors, *50.
Reichenbach, Charles. Armature bands overheat, 286.
Rennick, Walter M. Heating of commutator on rewound repulsion-induction motor, 492.
Reuter, Michael Armature bands overheat, 187.
——Determining number of poles in stator by use of compass, 377.
——Removing bar winding from stator of motor, 543.
Reynolds, H. R. Recommendations for lubrication of ball bearings, 541.
Ringness, George. Low-voltage generator will not excite, 235.
Roberts, E. E. G. Set of wedges for driving pinion from shaft, *193.
Roe, A. C. Calculation of rotor winding for squirrel-cage motor, 36
——Changing brush position and type of winding on d.c. motors, *292.
——Changing compound motor to special series type, *590.
——Changing slip-ring motor to squirrel-cage type, 284.
——Changing one-coil-per-slot windings to two coils per slot, *197.
——Changing phase and voltage of turbo-generator, 388.
——Changing the frequency of an induction motor, 244.
——Changing two-phase generator winding to three-phase, *436.
——Effect of turning rotor on split-phase motors, 142.
——Handy stitch for use when tying small cables, *144.
——Increasing thickness of slot insulation, 90.
——Laying in a chorded split-loop winding, *44.
——Low-voltage generator will not excite, 235.
——Replacing concentric chain winding on a generator with two-layer type, *542.
——Rewinding blowout coil, *148.
——Rewinding job simplified by changing coils, 341.
——Rewinding two-phase motors for three-phase operation, *97.
Roe, A. C., and D. H. Braymer. Changes in windings of single-phase motors, *225.
——Changing right-hand coil windings to left-hand, *177.
——Copper wire that is used in motor repair work, *364
——Cross or equalizer connections on lap windings, *26.
——Insulation on magnet wire for repair shop work, *415.
——Laying out and connecting a pyramidal winding, *322.
——Mush or hit-and-miss armature coils, *570.
——Recording rewinding data for cross connections, *121.
——Special insulation for wire used in repair work, *521.
Rowan, J. S. Compensators and primary resistance starters, *6.
Rylander, J. L. Testing insulation with high-frequency voltage, *129.

S

S., W. F. Easily constructed gage for aligning shafts, *339.
Salomonsen, Svend E. How to support a mule stand, *137.
——Proper babbitt for armature bearings, 32.
Samuels, S. H. Heating caused by carrying each phase of 3-phase circuit in separate conduit, 93, comment (C. Otto von Dannenberg), 336.
Schaphorst, W. F. Determining horsepower loss from friction in a bearing, *242.
——Determining power transmitted by friction wheels, *290.
——Determining size of pulley for fabric-base belts, *339.
—Eliminating trouble from static on belt-driven machines, 588.
—Size belt for drive, 578.
Schellenger, R.R. Trouble with solder, 381.
Schlegel, B. C. Cleaning skylights and windows, 36.
Scott, Wirt S. Electric heating can be used to advantage, *272.
Scribante, P. P. Increasing thickness of slot insulation, 90.
——Will two a.c. motors operate satisfactorily in parallel, 85.
Shapter, G. H. (see W. B. Potter).
Sigel, E. E. What causes heating of this cable box? 430.
——What size of belt is required for this drive? 578.
Simon, Henry. Making the slide rate add and substract percentages, *244.
Sizemore, Thomas A. Chain drives increase textile mill production, 434.
Slivinski, Hugo R. Mechanical maintenance policies and practices, *61.
Sloan, Frank W. Tests on motors do not check nameplate data, 428.
Smith, E. B. Emergency contactor made from a hinge, *39.
——Handy portable starting device for a.c. motors, *91.
Stafford, H. E. Changing speed and horsepower of induction motors, *148.
——Checking bearing alignment, 330.
——Comments on development and use of commutator stones, 181.
——Reducing operating and maintenance costs, *71.
——Testing insulation resistance of electrical equipment, 585.
——Tests on motors do not check nameplate data, 428.
——Trouble in keeping commutator bars straight, 427.
——What causes heating of this cable box, 581.
——Where should I use this wire? 493.
Stansel, N. R. Applying electric heat in industrial plants, *154.
Stead, E. E. Changing control to obtain lower motor speed, *581.
Steele, Harold H. Burned spots on collector rings, 531.
——Cause of heating of fuse studs, 530.
Stevens, R. C. Meters used as reverse current relays prevent racing of rotaries, *335.
Stevens, W. L. Clamp for straightening planks in laminated wall, *228.
——Determining power output of induction motors, *238.
——Drum controller for slip-ring motor rearranged for squirrel-cage motor, *288.
——Reconnecting 2,200-volt synchronous motor for 440 volts, *340.
Stirton, George W. Measurements required for bending conduit, *140.
Streeter, Claude O. Size belt for drive, 878.

T

TAYLOR, Dean W. Improper connections to motor cause of unusual performance, 94.
Trimm, George. Erecting and aligning a lineshaft drive, *398, *505.
Turner, R. B. Armature bands overheat, 286.

U

UMBERGER, C. L. Changing single-phase motor for three-phase operation, 530.
——Changing wire insulation, 534.
——Charging storage batteries, *583.
——Demagnetizing a lathe, *493.
——Why do these motors stall, 529.

V

VAN BRUNT, G. A. Maintenance practice and organization methods, *57.
——Reducing friction losses, *460.
Van Herk, P. Changing two-phase, four-wire system to two-phase, three-wire system, 236.
——European practice in laying steel-armored cables, 495.
——Graphic method of computing starting resistance for d.c. motors, *288.
Van Valkenburg, H. L. Comments on "compensators and primary resistance starters," 133.
Vining, R. N. Checking alignment of bridge on traveling crane, *192.
——Reducing operating and maintenance costs, 70.
——Testing for grounds and faulty insulation, 40.
——What causes heating of this cable box? *429.
von Dannenberg, C. Otto. Are transformer laminations injured by burning off oil and insulating compounds? 334.
——Capacity of transformer bank, 186.
——Changing two-phase, four-wire system to two-phase, three-wire system, 236.
——Determining power factor with watt-hour meters, *431, correction, 494.
——Effect of turning rotor on split-phase motors, 142.
——Heating caused by carrying each phase of 3-phase circuit in separate conduit, 336.
von Dannenberg, C. Otto (Continued):
——How single brushes caused reverse of polarity on generator exciter, 538.
——Is this relay connection scheme correct? 331.
——Low-voltage generator will not excite, *141.
——Misleading results sometimes obtained from magnets test, 233.
——Operating a.c. demagnetizer on direct current, *89.
——Overload protection for generators, *380.
——Paralleling open-delta-connected transformer bank with closed-delta bank, 492.
Vorderstrasse, R. C. Portable power connector for hand service, *336,

W

W., A. J. Specially-connected series motor substituted for shunt motor, 94.
——Unusual method of fishing through conduit by using conveyor wire, 494.
Wagoner, Arthur G. Inexpensive coil pulling and forming device, *543.
Walsh, J. M. Armature bands overheat, *376.
——Changing 25-cycle brake coil to 60-cycle service, 381.
——Hard-drawn or cast copper for commutators, 285.
——Layout of panel to control two generators, *495.
——Method of cleaning motor winding, 37.
——Proper babbitt for armature bearings, 32.
——Winding rectangular wire or edge, 425.
Warrick, W. A. Operating speed of roller chains, 241.
Way, E. L. Selecting belts for oily work, 286.
Weber, William L. Care of mica segments in commutators, 542.
——Development and use of commutator stones, *110 comments (E. H. Martindale), (H. E. Stafford), 181.
Weiss, Nicholas J. Changing 25-cycle brake coil to 60-cycle service, 381.
——Cutting fiber washers, *293.
——Determining number of poles in stator by use of compass, 378.
——Emergency method of making insulation trimmer and wedge driver, *590.
——Hard-drawn or cast copper for commutators, 285.
——Turning commutators, 88.
Winding data for growler, *284.
Westbrook, Francis A. Power service layout for small motor drives, *118.
Whitcomb, Arthur J. Compensators and primary resistance starters, *2.
——Problems of steel mill operation, *249.
——"What controller should I use for this drive?" *469.
Whitson, T. B. Comparison of insulation resistance and dielectric strength, 537.
——Misleading results sometimes obtained from magneto test, 139.
Williams, Chester A. Armature bands overheat, 187.
——Comment on "one man should be responsible for plant operation," *243.
——Proper babbitt for armature bearings, 32.
Williams, F. B. Drive for machine shop and pump, 184.
——Is this lamp consumption too high? 185.
Williamson, J. E. How variable speed control saves $15,000 a year, *434.
Wintersteen, Guy H. How to support a mule stand, 137.
——Low-voltage generator will not excite, 141.
Wisinski, I. F. Armature bands overheat, *187.
Witherspoon, J. K. Difference between 40-deg. and 50-deg. d.c. motors and their ratings, 239.
Wooley, W. C. Paralleling open-delta-connected transformer bank with closed-delta bank, *333.
Wray, A. B. Getting the most from silent chain drives, *456.
——Stopping breakage of gears, 87.

Y

YATES, W. C. Compensators and primary resistance starters, *5.
Young, William D. Selecting belts for oily work, 286.

Z

ZIMMERER Cecil W. Low-voltage generator will not excite, 141.
Zimmerman, J. M. Brush arcing on commutator, *87.
——Effect of turning rotor on split-phase motors, 142.
——Ground detectors for use on low-voltage systems, *432.
——Low-voltage generator will not excite, *141.
——Selecting commutator mica for direct current motors, *557.
——Trouble in keeping commutator bars straight, *427.

*Indicates illustrated articles